

06/22/2007 10/812947 Lewis

=> d his full

(FILE 'HOME' ENTERED AT 16:13:29 ON 21 JUN 2007)

FILE 'REGISTRY' ENTERED AT 16:13:43 ON 21 JUN 2007

L1 5 SEA ABB=ON PLU=ON AL.AS.GA.IN.N.P/MF
L2 4 SEA ABB=ON PLU=ON AL AS GA IN N P/ELF

L3 151025 SEA ABB=ON PLU=ON MG/ELS
L4 13665 SEA ABB=ON PLU=ON BE/ELS
L5 204075 SEA ABB=ON PLU=ON ZN/ELS
L6 1 SEA ABB=ON PLU=ON CARBON/CN

FILE 'CAPLUS' ENTERED AT 16:16:03 ON 21 JUN 2007

L7 18 SEA ABB=ON PLU=ON L1 OR L2
L8 38573 SEA ABB=ON PLU=ON L3/MOA
L9 2803 SEA ABB=ON PLU=ON L4 (L) MOA/RL
L10 25422 SEA ABB=ON PLU=ON L5 (L) MOA/RL
L11 11697 SEA ABB=ON PLU=ON L6 (L) MOA/RL
L12 69790 SEA ABB=ON PLU=ON (L8 OR L9 OR L10 OR L11)
L13 3 SEA ABB=ON PLU=ON L7 AND L12
D IBIB ABS HITSTR HITIND 1-3
L14 0 SEA ABB=ON PLU=ON US20050051804/PN

FILE 'WPIX' ENTERED AT 16:24:51 ON 21 JUN 2007

L15 1 SEA ABB=ON PLU=ON US20050051804/PN
D IFULL

FILE 'CAPLUS' ENTERED AT 16:26:24 ON 21 JUN 2007

L16 1 SEA ABB=ON PLU=ON JP2005085852/PN
L17 18 SEA ABB=ON PLU=ON L7 NOT L16
SEL RN L16
L18 32780 SEA ABB=ON PLU=ON (106097-44-3/B1 OR 25617-97-4/B1)
L19 1 SEA ABB=ON PLU=ON L16 AND L18
D IBIB ABS HITSTR HITIND
L20 15 SEA ABB=ON PLU=ON L7 NOT L13
D IBIB ABS HITSTR HITIND 1-15

FILE 'INSPEC' ENTERED AT 16:39:03 ON 21 JUN 2007

L21 2 SEA ABB=ON PLU=ON (AL SS(S) IN SS(S) GA SS(S) AS SS(S) P SS(S) N
SS)/CHI
D IALL 1-2

FILE 'REGISTRY' ENTERED AT 16:49:42 ON 21 JUN 2007

L22 61 SEA ABB=ON PLU=ON GA.N/MF
L23 134 SEA ABB=ON PLU=ON GA N/ELF

FILE 'CAPLUS' ENTERED AT 16:50:00 ON 21 JUN 2007

L24 31982 SEA ABB=ON PLU=ON L22 OR L23
L25 3043 SEA ABB=ON PLU=ON L24 AND L12
SET LINE 250
SET DETAIL OFF
E DOPING+ALL/CT
SET LINE LOGIN
SET DETAIL LOGIN
L26 713347 SEA ABB=ON PLU=ON DOPANT? OR DOPING OR IMPUR? OR ION(W) IMPLAN
T? OR DOPE?
L27 2283 SEA ABB=ON PLU=ON L25 AND L26

06/22/2007 10/812947 Lewis

SET LINE 250
SET DETAIL OFF
E BAND GAP+ALL/CT
SET LINE LOGIN
SET DETAIL LOGIN
L28 121028 SEA ABB=ON PLU=ON BAND GAP OR BANDGAP? OR ENERGY? GAP? OR
FORBID? (2A) GAP OR FERMI? (2A) LEVEL? OR SPIN (2A) GAP?
L29 207 SEA ABB=ON PLU=ON L27 AND L28
S (ALUMINUM OR INDIUM OR PHOSPHORUS OR ARSENIC) /CN
FILE 'REGISTRY' ENTERED AT 16:56:29 ON 21 JUN 2007
L30 4 SEA ABB=ON PLU=ON (ALUMINUM OR INDIUM OR PHOSPHORUS OR
ARSENIC) /CN
FILE 'CAPLUS' ENTERED AT 16:56:29 ON 21 JUN 2007
L31 660223 SEA ABB=ON PLU=ON L30
L32 27 SEA ABB=ON PLU=ON L29 AND L30
L33 2 SEA ABB=ON PLU=ON L32 AND BUFFER?
L34 2 SEA ABB=ON PLU=ON L33 NOT (L7 OR L16)
D IBIB ABS HITSTR HITIND
D IBIB ABS HITSTR HITIND 2
L35 25 SEA ABB=ON PLU=ON L32 NOT (L7 OR L16 OR L33)
D IBIB ABS 1-25